



Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT
Road History Data Sheet

General							
Zone	Ward No.	Ward Name					
DASARAHALLI	14	Bagalakunte					
Street ID	Street Name	Significant Landmark					
W0691, W0695, W0687, W0536, W0538, W0520, W0683, W	NA, 1st Main Rd	Vijayalakshmi Layout					
Segment No.	Total Length (m)						
14/C-W0691/S114406	443.49						
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	61.11	77.500504	13.055842	77.499943	13.055889	Vijayalakshmi Layout 3rd cross	Dead end
2	35.72	77.500921	13.055873	77.500862	13.055556	Vijayalakshmi Layout 3rd cross	Dead end
3	59.38	77.499991	13.055608	77.500536	13.055561	Vijayalakshmi Layout 1st Cross	Dead end
4	68.12	77.499894	13.055347	77.500520	13.055295	Vijayalakshmi Layout 3rd cross	Dead end
5	43.35	77.500606	13.055285	77.501001	13.055233	Vijayalakshmi Layout 1st Cross	Dead end
6	58.72	77.500573	13.055561	77.501108	13.055477	Vijayalakshmi Layout 3rd cross	Dead end
7	117.09	77.501440	13.055915	77.500926	13.054988	Vijayalakshmi Layout 1st Cross	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements of CC Roads drains and other works at Vijayalakshmi Layout in Ward No 14 Bagalagunte	99950000	2020-21
Year	Type of Work	Other Work Type
2020 - 2021	Others	CC roads and drains
Tender	Work Details	Job No. / Work Code
Not a Tender		014-20-000113
Work Order No.	Work Order Date	Period of Extention
	08/04/2020	

Zone: DASARAHALLI

Ward No: 14

Ward Name: Bagalakunte

Street ID: W0691, W0695, W0687, W0536, W0520, W0683, W

ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಅಭಿಯಂತರರು
ಬಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073.

Defect Liability Period From

08/04/2020

Defect Liability
Period To
07/04/2021Multiple road involved with the
same Job No/ Work Code #
No

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BIMP/PWD)

Phone No.
7483661463

E-Mail ID

Expenditure Booked \ Released (Rs)
99942560 00

Field Inspection Details

Number of Trees

2

Any Other Information

works complete

Name

Chelan K M

Date of Inspection

07/08/2020

Remarks

works complete

Category

Drain Condition

Image

Photo Remark



Footpath Condition



Road Condition



Segment End



Segment Start



Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE-DAS	10/08/2020	06/09/2020	Approved.
EE	K.S Idrus	07/08/2020	06/09/2020	Completed
AEE	M B Jayakumar	07/08/2020	06/09/2020	works complete

Zone: DASARAHALLI

Ward No: 14

Ward Name: Bagalakunte

Street ID: W0691,

W0695,

W0687,

W0690

ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಬಾಲಕ ಅಭಿಯಾನಕರ್ತರು
 ಬಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
 ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
 ಬೆಂಗಳೂರು-560073.

Handwritten signature and initials.

Chetan KM AE

07/08/2020

Chetan K M

07/08/2020


06/09/2020

works complete

06/09/2020

Completed

Cap


ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಧೀಯಂತರು
ಟಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಜಿ, ಪಿ.ಪಿ.ಎಂ.ಒ.
ಬೆಂಗಳೂರು-560073.